

Foreseer 5.0



Contents

Description	Page	Description	Page
Contents	1		
Overview	2		
Patch Release 5.0.71.0	2		
Patch Release 5.0.72.0	2		
Patch Release 5.0.73.0	2		
Patch Release 5.0.74.0	2		



Powering Business Worldwide

Overview

The following sections list the changes in each of the designated Foreseer patches:

Patch Release 5.0.71.0

Fixed a logic error that caused manually added channels to appear to be installed correctly, but would then have no values.

Patch Release 5.0.72.0

Fixed a problem with persistent global variables not being saved. Now, persistent global variables retain their values when Foreseer is restarted.

Patch Release 5.0.73.0

Fixed a problem with the file containing the persistent global variables. Prior to this patch, persistent variables would work correctly the first time Foreseer was started, but they would not be saved after restarting Foreseer.

Patch Release 5.0.74.0

Fixed a problem with Webviews templates and iFrame objects. Prior to this patch, if you created a Webviews template from a Webviews page containing an iFrame object, any pages created from that template would not contain the iFrame object.

Eaton Corporation
Electrical Group
1000 Cherrington Parkway
Moon Township, PA 15108
United States
877-ETN-CARE (877-386-2273)
Eaton.com

© 2010 Eaton Corporation
All Rights Reserved
Printed in USA
Publication No. EH02606004E
February 2010



PowerChain
Management®

PowerChain Management is a registered trademark of Eaton Corporation.

All other trademarks are property of their respective owners.